TSL Distro Guide Version History

For the latest version of the TSL Distro Guide, visit www.tsllighting.com/distroguide

Changelog from Q4 2024 to Q1 2025

I.   312 added

Changelog from Q3 2024 to Q4 2024

II.   131 removed

Changelog from Q2 2024 to Q3 2024

III.   115 added

IV.   Version number changed to match internal use

Changelog from Q1 2024 to Q2 2024

V.   114 added

VI.   139 added

VII.   339 added

VIII.   336b added

IX.   Variable RCD info added

Changelog from Q3 2023 to Q1 2024

X.   HP36d added - this is an HP36c with <u>no</u> 16A/1 Utility

XI.   3P6a added - this is a 3P6 that has different Utility Power outlets. a 3P6 also has 250A Powerlock whereas the

3P6a has 200A Powerlock.

Changelog from Q2 2023 to Q3 2023

XII.   3613 added

Changelog from Q1 2023 to Q2 2023

I.   335 Breakers changed

Changelog from Q1 2022 to Q1 2023

II.   Type 3611 retired

Changelog from Q2 2020 to Q1 2022

III.   HP72a added

IV.   HP72e added

V.   163, 3P4, 3P6 & 3P7 photo updated. Unit remains unchanged.

VI.   HP72 incoming breaker information corrected, there is no variable ELR

VII.   HP18e added to differentiate from HP18a

Changelog from Q3 2019 to Q2 2020

I.   HP36 renamed HP42

II.   HP36a renamed HP42a

Changelog from Q1 2019 to Q3 2019

I.   Breaker Information for 365 corrected

II.   HP18a renamed HP18d

III.   New style HP18a added

IV.   HP72 renamed HP72b

V.   New style HP72 added

VI.   367a added

For any further information or error corrections, please visit the new link or contact hiredesk@tsllighting.com